Project No.	Client	Location	Boring No.	Monitoring Well No.	Date
01105	Metro Car Wash	2950 Harbor, CM	CB-3	N/A	August 8, 2005
PID	BLOWS/ft. Sampler	DEPTH in feet	USCS Designation & Soil Type	Color	Secondary Characteristics
0	4-8-15	5	CL-Sandy Clay	Light Brown	Stiff, S1 Damp, No Odor
0	8-18-20	10	SM-Silty Sand	Medium Brown	Loose, Dry
0	7-10-17	15	CL-Silty Clay	Tan to Grey	Stiff, Dry
0	7-12-21	20	CL-Gravelly Clay	Light Grey	10% Gravel
0	12-20-27	25	CL-Silty Clay		
0	16-18-20	30			
0	22-27-45	35	SM-Silty Sand		M. Dense
0	22-28-35	40	CL-Silty Clay	Olive Green	Stiff, Damp
0	36-50/5"	45	SM-Silty Sand	Tan	Very Dense, Moist
0	42-50/5"	50			
0	37-50/5"	55			
0	32-38-50/5"	60			
0	30-35-50/4"	65			
0	25-50/4"	70		Light Brown	Wet
0	22-50/5"	75	SP-Poorly Graded Sands		
Field Engineer	Drilling Contractor	Drilling Foreman	Boring terminated at 75 feet below grade. Groundwater at 67'. Boring backfilled with soil of origin and capped with bentonite plug (2'). Resurfaced with concrete		
M. Anselmo	J & H	Conrad			